# 2018 REGIONAL STORMWATER



0

PIPE WAS PATCHED YEARS AGO AND ALLOWED FOR INSUFFICIENT FLOW , ALSO PONDING BY BASIN BECAUSE ORIGINAL BASIN WAS SET TO HIGH.

PROBLEM

# SUNRISE DRIVE




























### PROBLEM


## GUARDRAIL POST WAS DRIVEN THROUGH PIPE , CAUSING EROSION


## 22 SNAKE RIVER ROAD















### PROBLEM

POND OVERFLOW WATER FROM ABOVE CAUSING MAJOR EROSION, WITH NO SYSTEM BELOW TO CONVEY THE WATER

# RIDGEVIEW ACCESS ROAD




































## POUND LANE SADDLE CLUB


#### PROBLEM

WATER FROM ROADWAY PONDING AND FLOODING ADJACENT PROPERTY, WITH NO STORM SYSTEM IN PLACE.






















PROBLEM

WATER FROM ROADWAY WAS FLOODING ADJACENT PROPERTIES WITH NO STORM SYSTEM IN PLACE.

## 16<sup>TH</sup> AND POPLAR
































## FAIRGROUNDS MUD SLIDE



DRAIN-GRATE BECAME CLOGGED WITH DEBRIS AND WATER WAS NOT ABLE TO FLOW INTO STORM SYSTEM.

PROBLEM

















# SWEEPING TOTALS 2018





